

VIRGINIA ZONE
Active Pits

DS/lj 12/30/2019


| Pit Name | Legal | Price/cyd | Notify Public Works of Permit | | Locked Key Needed | Comments/Special Conditions |
|----------------------------|--------------------|-----------|-------------------------------|----------|-------------------|---|
| | | | Y/N | District | | |
| 1. Admiral Rd.- 788 | SW-SE 33-56-18 | \$1.50 | Y | 6 | N | PW and Township stockpiles <u>east</u> of road. Various other stockpiles on <u>west</u> side and use must be approved. Adjacent timber set up for sale to allow future expansion. Combined with McDavitt Pit. |
| 2. Anchor Lake | E ½-SE 15-56-17 | \$1.50 | N | 6 | N | Limited material, sandy, limited rock. Communication tower adjacent (lease). Possible Septic Sand. Steep face. Stripping needed. |
| 3. Colombe | NW-SW 24-59-20 | \$1.50 | Y | 7 | N | Small pit, rocky mixed material, crushed by PW in the past. Observe south bank (steep) property line. Needs to have timber removed and stripped. |
| 4. DuPont | SW-SW 7-57-19 | \$1.50 | Y | 7 | Y | Currently pit is depleted and only small private sales possible. Pit stockpiles owned by Public Works. Water management within pit always an issue. Southern part of pit has select sand. |
| 5. Elbow Lake (aka 315) | NE-SE 9-57-18 | \$1.50 | Y | 6 | Y | PW Class 5 piles from 2019. Good Class 5 material, but needs overburden removal in places. Storm Water berms located on southeast. |
| 6. Finberg | SE-SE 32-55-21 | \$1.50 | Y | 7 | Y | Land Department stockpile. Sandy, but crushable. |
| 7. Greenrock | SW-NW 32-60-21 | \$1.50 | N | 7 | Y | Sand, fine gravel with little cobble or binder, possible septic quality in places. Bank below adjacent tower closed. Canister site adjacent. Possible expansion to east with stripping. |
| 8. Harris | N ½-SW 28-56-15 | \$1.50 | Y | 6 | Y | PW has Class 5 from 2018 crushing. Excellent crushing and blacktop pit, clean sand, rock and binder. PW and Township stockpiles. |
| 9. Linwood Lake | SE-SE 21-56-14 | \$1.50 | N | 6 | N | Sand, fine gravel. Small pit used by cabin owners in area. |
| 10. North Balkan | NW-NW 3-59-20 | \$1.50 | N | 7 | Y | Sandy, used as possible septic sand. No taking from signed northwest bank (MNDOT). Stripping needed. |
| 11. Norway Rd.-312 | SW-SE 17-56-18 | \$1.50 | Y | 6 | Y | PW has Class 5 pile from 2018 crushing on County Fee portion of pit. Sandy with small rock, barely adequate binder. |
| 12. Pungy Stick | SE-NE 19-57-13 | \$1.50 | N | 6 | N | Small pit west side #110(Forest Highway 11). Cobbly and rocky. Used as a wood yard. |
| 13. Skibo | SW-SE 21-58-13 | \$1.50 | N | 6 | Y | Rocky. Observe property boundary south side. |

VIRGINIA ZONE
Active Pits

| Pit Name | Legal | Price/cyd | Notify Public Works of Permit | | Locked Key Needed | Comments/Special Conditions |
|-----------------------------------|-------------------|-----------|-------------------------------|----------|-------------------|---|
| | | | Y/N | District | | |
| 14. Sunset Lake | NW-NE 25-59-21 | \$1.50 | Y | 7 | Y | PW Public Works and Balkan Township have Class 5 piles from 2019 crushing. Major PW use. Storm water management always problematic. Berms and retaining ponds adjacent to stream. Hibbing Tac Land gravel pit adjacent. |
| 15. Tiger Lily (aka Whiteface) | SE-SW 2-55-15 | \$1.50 | Y | 6 | Y | PW has Class 5 pile from 2018 crushing. Long term multipurpose pit, good mix of materials. Observe property marker on east side. East side off limits. |
| 16. West Mud Lake | SW-NW 15-57-12 | \$1.50 | N | 6 | N | Small site. Remote. West of Seven Beavers Grade. Very rocky material. |

DS/lj 12/30/2019

Virginia Zone Gravel Pits



Prepared By: Dave Skurla
 Map Created: 12/23/2019
 TRS: Virginia Zone
 Disclaimer:
 This is a compilation of records as they appear in the Saint Louis County Offices affecting the area shown. This drawing is to be used only for reference purposes and the County is not responsible for any inaccuracies herein contained.

0 10 Miles

★ --Gravel Pits

